

Recommendation for edge treatments

For SWISSCDF with Rubio Monocoat Oil Plus 2C A

Description

Rubio Monocoat Oil Plus 2C A or Oil Plus 2C A+B is the newest state-of-the-art product for both painting and protecting your wood with a single coating. The bonding of the molecules of natural oil and wood fibres creates a particularly high resistance against liquids and household chemicals and increases abrasion resistance. The combination of wood protection oil (A) and accelerator (B) ensures quick drying.

Specific characteristics:

- 0% VOC, solvent-free
- Low consumption - 1 litre covers 30 to 50 m²
- Simple, completely smooth application at the first attempt
- Simple cleaning; can be applied to virtually all types of wood as well as to veneers and MDF, HDF and CDF
- Long-lasting
- Heat-resistant up to 100 °C
- Quick hard-drying

Technical characteristics

RMC Oil Plus 2C (A):

- Physical condition at 20 °C: liquid
- Colour: light yellow
- Odour: natural oil
- Flash point: > 99 °C

RMC Accelerator (B):

- Physical condition at 20 °C: liquid
- Colour: transparent
- Flash point: > 160 °C (closed)

Instructions for use

1. For treating the edges, they need to be dry and free from dust and grease. If necessary, remove remaining dust with RMC Cleaner.
2. As soon as the cleaned edges are dry, apply a small amount of RMC Oil Plus 2C A with a sponge or a cotton cloth (shake oil thoroughly).
- 2a. If you use component B (accelerator), carefully mix components A and B with a ratio of 3 to 1 for about 1-2 minutes.
3. Leave on for some minutes. Remove excessive oil with a cotton cloth within 15 minutes.
4. Remove liquid oil residues on the coated surface with a cotton cloth immediately.
5. The oil is 100% dry after 24-36 hours and the product is then ready for use.

After 5 days (Oil Plus 2C A+B) or 14 days (Oil Plus 2C A) of crystallisation, the surface is capable of bearing the full load. Protect against intense moisture for the first days.

Dried oil on the coated surface

- Dried oil residues on the coated surface can be removed with the RMC Oil Remover .
- Apply the RMC Oil Remover with a cotton cloth or a sponge, leave on for a few minutes, then remove the oil stain Repeat, if necessary.
- Refrain from excessive pressure to avoid shiny spots or abrasions.



CAUTION

Rubio Monocoat must not be diluted!
Cloths impregnated with the product are self-flammable and must be neutralised in water after use.